

### App Note 1015: W204 Factory iPod Connector issues

When installing the Video-In-Motion Module on the W204 with the factory ipod option there may be issues with the radio not turning on or with intermittent operation. This is often due to a problem with a defective factory ipod T-Harness. The issue lies in the receiver end of the harness (the end without the locking lever). Look at the connector once it is locked together with its mating connector and check that the connector pins have not become unseated. The ends of the pins should all sit at a uniform height.

